0036

From:

Karl Houskeeper

To:

shawn.baker@hiawathacoal.com

CC:

Angela Nance; Daron Haddock; Suzanne Steab

Date:

4/6/2009 2:39 PM

Subject:

March 2009 Inspection Report Attachments: Bear Canyon March 2009.pdf

Shawn,

Attached is the March 2009 inspection report for Bear Canyon.

Thanks,

Karl

Chitgoing Co150025



State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Permitee: HIAWATHA COAL CO INC

Company

Operator: HIAWATHA COAL CO INC

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Site: BEAR CANYON MINE

Representatives Present During the Inspection:

Address: PO BOX 1240, HUNTINGTON UT 84528

Shawn Baker Environmental Coordinator

OGM Karl Houskeeper Environmental Scientist III

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

10,991.83	Total Permitted		
40.46	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Inspection Report

Permit Number:	C0150025
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, March 11, 2009
Start Date/Time:	3/11/2009 8:00:00 AM
End Date/Time:	3/11/2009 1:00:00 PM
Last Inspection:	Thursday, February 19, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear, Temp. 14 Deg. F.</u> InspectionID Report Number: <u>1942</u>

Accepted by: jhelfric

3/11/2009

Mineral Ownership	Types of Operations		
✓ Federal	✓ Underground		
☐ State	☐ Surface		

☐ County ☐ Loadout

☑ Fee ☐ Processing
☐ Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

inspector's	Signature:

Harle Manskuper

Date

Wednesday, March 11, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Continuation Sheet

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 11, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	•				
4	Dameita Change To 1 D	Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<u> </u>			
2.	Signs and Markers	<u> </u>		<u> </u>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<u> </u>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	V	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V			
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		Y	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 11, 2009

Page 3 of 3

2. Signs and Markers

The ID signs contained the necessary information for CW Mining.

4.a Hydrologic Balance: Diversions

Checked the diversion area referred by Division Hydrologist April Abate in her technical field visit at the Main Portal Access Road junction with the pad area by the coal loadout. It appears that a hump of sediment laden snow has been pushed near the existing berm. The hump of snow is higher in elevation than the current berm. It appears that the berm concern noted by April starts out low and becomes higher as it moves away from the road diversion and extends across the culverted road access to the pad area. With the placement of the snow there now appears to be a variation in the berm. No water was being diverted through the area of concern noted by April during my partial inspection. Due to the existing temperature during the inspection no water or snow melt was taking place through the diversion. Evidence did show that previous drainage has flowed through the designed diversion with no indication of bypass through the berm. A verbal report of my findings from the inspection was given to April Abate.

18. Support Facilities, Utility Installations

Inspected the septic drain field adjacent to the bathhouse as a follow up to potential concerns expressed by MSHA. My inspection showed that there were small areas of ice in the parking lot area by the septic drain field. No water was surfacing during the inspection. Mark Reynolds (company) explained that following the MSHA inspectors concern that they investigated the site and that this area is due to be redesigned through a permit amendment with the Division for the parking lot expansion. Any concerns including, potential maintenance, potential drain field failure with the septic system will be addressed at that time. Until the parking lot expansion is approved by the Division the company has started to pump the septic tanks keeping the elevation lowered in the tanks in an effort to avoid any water surfacing in the parking lot area. Any potential water surfacing from the drain field is above sediment pond C. The company plans to monitor the area to assure that their pumping efforts have stopped the water from surfacing in the parking lot area.